

SIEMENS

If the 840Di SW 1.1 is installed on an existing Version 1.0, then the NCK upgrade will not run. Check the NCK version using the HMI Explorer or NC MD – it should be 01.01.00.00. (N18040 \$MN_VERSION_INFO[0]="62.05.02 old version)

Remedy:

The NCK software installation must be separately started.

Under WinXP, start 840Di SW -> installs -> apps -> nck -> setup.exe.

