

Initiating the shutdown of the PCU 50 from the PLC

HMLexit.exe can be found in E:\SITOP as from basic software release 07.04.00.
This is used to shut down the PCU on USV systems.

HMLexit.exe can be started from the PLC with the hotkey function described in DOConCD in Chapter 'Expand User Interface (BE1), Configuring OP Hotkeys and PLC Keys'.

A Keys.ini has to be generated in the user path with the following entries.

```
[KeyConfiguration]
KEY50.0= Task :=51
```

An entry in USER\regie.ini starts HMLexit.exe

```
[Taskconfiguration]
```

```
Task51 = name := OEMFRAME, cmdline :="E:\\SITOP\\HMLexit.exe", Timeout:= 10000,
PreLoad := False
```

The shutdown is started by entering the value 50 dec. in DB19.DBB10.